Abstract.
This paper describes differences between models of a rectangular shaped reinforced concrete floor with ribs, commonly used by structural designers. Comparison analysis proves significant differences in result obtained from differentmodels. Incompatibility is shown bothin static as well as in modal analysi